





Contact us at your convenience.

[P] 515.890.0852  
[E] nic@redrockcontrols.com

Send payments to:  
Red Rock Controls  
107 W Robins St  
Graettinger, IA 51342



Red Rock Controls  
107 W Robins St  
Graettinger, IA 51342



Red Rock Controls  
107 W Robins St  
Graettinger, IA 51342



We want to present an opportunity for you to save money on circuit card assembly repair costs. We're a component level electronics repair service with a centralized location and competitive service costs. Our goal is to lower maintenance costs in agricultural production facilities, golf courses and sports fields by repairing electronic controls for up to 40% less than typical repair centers. We currently service Aerotech, Airstream and Toro but are willing to help with whatever need you may have. With our personal experience, training and education, we can help you run your operations smoothly and with the most cost effective means possible. Keeping your downtime to a minimum is our priority. In today's economic conditions, businesses need every edge they can get. RRC will make your dollar go farther.

**Red Rock Controls offers test and repair services to the nation's leading suppliers of ag industry control systems used for ventilation heating and cooling in livestock confinement buildings as well as irrigation controllers for golf course and sports field greens. We're prepared to meet your needs; contact us for information on how to obtain our service with a quick turn-around and competitive price.**

## Services

Tc5-1n4f1a	Expert-VT110	TC4-2N6F	Farm Hand Stage Master
Tc5-1n5fab	Expert-VT212	TC4-2V2S	Phason PEC
Tc5-1n8fa	TC1-1SD	TC4-2V4S	Phason PEC+
Tc5-1v6sa	TC1-C	TC4-4M	Aerotech SB3500
Tc5-1v10sa	TC1-CD	TC4-4SD	Aerotech SS5124
Tc5-2n4sa	TC1-MFS	TC4-4SZ	Aerotech ST5124
Tc5-2v2sa	TC1-NV	TC4-8SD	WH-T-21A
Tc5-2v4sa	TC1-Slave	TC4-12SD	CVWS-T-11HA
Tc5-2v4sa_stir	TC3-NV4	TC4-MS1	WH-T-42
Tc5-2v4sw	TC3-NVH2	TC4-MS2	CWS-T-11HA
TC5-2V7SA	TC3-NVH4	TC4-MS3	
Tc5-2v8s	TC3-1N4F	TC4-NV2S	
Tc5-3n3sa	TC4-1CH	TC4-NVS	
TC5-8SDA	Tc4-1n4f1	TC4-NVSP	
Tc5-12sda	TC4-1N6F	TC4-T1	
TC5-NV2SA	TC4-1T7S	TC4-T10	
TC5-T1A	TC4-1V1S	TC4-T3O	
TC5-T6A	TC4-1V2S	TC4-T4	
SP-2	TC4-1V3S	TC4-T5	
Expert-2v3sa	TC4-1V6S	TC4-T6	
Expert-N	TC4-1v10s	Hired Hand Evolution 3000	
Expert-PN110	TC4-1VH	3001	
Expert-VT100	TC4-1VHB	Farm Hand Swine Finisher	

## Return Procedure

**IDENTIFY** which circuit board assembly is defective (the entire control unit may be returned for service if you can't identify the faulty circuit board).

**REMOVE** the unit. The faceplate control assembly should be returned as a whole, with the faceplate and knobs attached. The main, slave or rear circuit board assemblies may be returned with or without the case. Sometimes it is easier to remove the circuit board from the case than it is to remove the entire case from the wall.

**SHIP** the defective unit to the address listed on the back this brochure once securely boxed. Repairs may be shipped to RRC by UPS, FedEx, USPS or any other carrier of your liking. \$300 insurance on each returned assembly is highly recommended.

Most repairs can be completed within 10 working days.

## Repair Pricing

Aerotech Series 4 Front Panel	\$125
Aerotech Series 4 Back Panel	\$125
Aerotech Series 5 Front Panel	\$125
Aerotech Series 5 Back Panel	\$125
Airstream TC-4 Series Front Panel	\$125
Airstream TC-4 Series Back Panel	\$125
Airstream TC-4 Series Slave Board	\$125
Airstream TC-5 Series Front Panel	\$125
Airstream TC-5 Series Back Panel	\$125
Airstream TC-5 Series Slave Board	\$125
Expert VT or PN LCD Display Board	\$200
Expert VT or PN Switch Board	\$150
Expert VT or PN Main Processor Board	\$175
Expert VT or PN Variable Speed Control Board	\$110
Expert VT or PN Power Supply Board	\$110
Expert VT or PN Relay Board	\$100
Varifan ECS Series Front Panel	\$150
Varifan ECS Series Rear Panel	\$150

Controllers usually contain multiple circuit boards. The repair prices above are based on each individual circuit board assembly.

\* Iowa residents without a tax exemption will be charged an additional 7% sales tax.

**“Keeping your downtime to a minimum is our priority.”**

Nic Stockdale, Owner

## Contact

**PHONE** 515.890.0852

**EMAIL** [nic@redrockcontrols.com](mailto:nic@redrockcontrols.com)

